


Barge Journey: 5,600 km



HOGING SEQUENCE:

1. CONNECT FROCING AS SHOWN ON LEGANN-FALLS LOOSE.

2. LIFT WSR SLOWLY WATCHING FOR CLISADELES.

3. IF ONE TEMPORARY SADDLE COMES IN THAN 3", LOWER CRANES AND ADJUST IN LOWER LIFTING BEAM USING CLAMP—ON SLODLES AS REQUIRED.

4. LIFT WITH CRANES UNTIL BOTH SADDLES INCHES AND ONLY THEN TICHTEN LISTABILIZATION.

R SHADILE

-PARTED AT 1201 SHACKLE

BARNHART

Cargo: Roro to/from Barge

- Steam Generator Stators
- 39'x 15'4"x 15'8"
- 845,000 lbs. each







BARNHART





21500 X 10' ARTED AT 1201 SHACKLE 15 000 LBS AVERTICALS

BARNHÀRT




Permitted Transports

- 236'5"x 20'4"x 18'8"
- 1,336,603 lbs.



Permitted Route 270 Miles



Safety

- 538 hours pre hauling surveys: Obstacles, Pavement, Bridge
- 19 bridges engineered 15 required on site monitoring each transport,
 3 required inspections before approval
- Two weigh-ins for each transport
- 8 parking areas secured with two alternates
- Three prime movers, two spares
- Daily job hazard analysis with BCR crew and all supporting team
- Barnhart Standard Operation Procedures
- Barnhart qualification training for all crew



Result

- 7393 Person Hours
- Zero Accidents
- Zero incidents
- Zero First Aids
- Zero Recordables
- Zero Citations
- Zero damage to infrastructure







BARNHÀRT